


PROFORMA REGARDING SAFE DRINKING WATER AND
SANITARY CONDITION CERTIFICATE

NO.....267.....

Date.....09.07.2024.....

It is certified that an inspection team headed by Er. Harishankar Kumar, Assistant Engineer, P.H.Sub-division, Dalsinghsarai inspected ST. JOSEPH'S PUBLIC SCHOOL, MSV Nagar Dalsinghsarai, (Samastipur) Bihar on 09.07.2024 and found that the ST. JOSEPH'S PUBLIC SCHOOL, MSV Nagar Dalsinghsarai, (Samastipur) has safe drinking water facilities for the students and members of staff of the institution and is maintaining hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T.Govt.

The above valid for a period of 6 Months


Assistant Engineer,
P.H.Sub-Division, Dalsinghsarai.
P.H Sub. Division
Dalsinghsarai

To,

Principal,
ST. JOSEPH'S PUBLIC SCHOOL,
MSV Nagar Dalsinghsarai,
(Samastipur)